

DEZINCIFICATION OF COPPER ALLOYS IMPELLERS USED FOR POTABLE WATER PUMPING

M. Rotel*, R. Starostin*, S. Tamir* and P. Letai**

*** Israel Institute of Metals, Technion R&D ltd., Israel**

**** Mekorot, Water Co. Ltd.**

e-mail:malka@tx.technion.ac.il

Introduction

- In this paper we present the results of investigation of impellers failure made of:
- Silicon brass: UNS C87500 - *14.6%Zn, 3.75%Si*
- Silicon bronze: UNS C87600 - *6.6%Zn, 3.37%Si*
- The two types of impellers failed after very short time.
- Dezincification is less expected when zinc content is below 15%

Corroded Impeller

UNS C87600: Zn 6.6%, Si 3.8%



Corroded Impeller

UNS C87500: 14.6%Zn, 3.75%Si



Corroded Impellers

UNS C87500: 14.6%Zn, 3.75%Si





UNS C87600: 6.6% Zn, 3.8%Si




RESULTS

Cross-Section

UNS C87500: 14.6%Zn, 3.75%Si







UNS C87500: 14.6%Zn, 3.75%Si



UNS C87500: 14.6%Zn, 3.75%Si

CrossSections

- Layer type dezincification
- Erosion of copper layer



UNS C87600:6.6%Zn, 3.37%Si



**Edge of Failed Impeller
Blade:**

- COPPER LAYER**
- CRACKS BETWEEN
COPPER LAYER AND
UNCORRODED ZONE**


Microhardness

UNS No.	Yellow Region HV	Pink Region HV
C87500 14.6%Zn, 3.75%Si	195-210	40-60
	195-200	55-60
C87600 6.6%Zn, 3.37%Si	170-190	100- 105

Metallographic Examinations

UNS C87500:


14.6%Zn, 3.75%Si



Copper layer

UNS C87600:

6.6%Zn, 3.37%Si




- Copper rich zones at grain boundaries
- Cracks at grain boundaries

SEM and EDS


Cross-section

UNS C87600:6.6%Zn, 3.37%Si



	1	2	3	4	5
Si		5.4	3.3	2.7	2.2
Cu	100	88.4	90	88.7	90
Zn		6.2	6.6	8.5	7.6

UNS C87500: 14.6%Zn, 3.75%Si




C			
	1	2	3
Si	4.7	3.6	3.6
Cu	82.8	83.4	83.4
Zn	12.5	14.1	14.1


SEM and EDS

UNS C87500: 14.6%Zn, 3.75%Si

UNS C87600: 6.6%Zn, 3.37%Si




C	1	2	3
Si	4.7	3.6	3.6
Cu	82.8	83.4	83.4
Zn	12.5	14.1	14.1



	1	2	3	4	5
Si		5.4	3.3	2.7	2.2
Cu	100	88.4	90	88.7	90
Zn		6.2	6.6	8.5	7.6

Grains with different Si content

Higher Si content at grain boundaries



UNS C87500: 14.6%Zn, 3.75%Si

Corroded porous layer- copper layer

A

	1	2
Si	0.3	3.2
Cu	99.6	82.9
Zn	0.1	13.9



Near corroded layer – Difference in Si content

B

	1	2
Si	3.6	5.4
Cu	83.2	81.3
Zn	13.3	13.4

UNS C87600:6.6%Zn, 3.37%Si

CROSS -SECTION IMPELLER BLADE



Corroded area

- Copper rich zone on grain boundaries
- Cracks on grain boundaries

Near corroded layer

- Higher Si content in grain boundaries

	A1	A2
Si	2.2	3.1
Zn	4.9	7.9
Cu	92.9	89.0



A1


2

	1	2
Si	1.1	2.4
Zn	-	6.8
Cu	98.9	90.8

A2

λ

	3	4
Si	2.8	2.2
Zn	8.0	6.5
Cu	89.2	91.3



Microhardness

UNS No.	Yellow Region HV	Pink Region HV
C87500 14.6%Zn, 3.75%Si	195-210	40-60
	195-200	55-60
C87600 6.6%Zn, 3.37%Si	170-190	100-105

Summary

UNS C87500: 14.6%Zn, 3.75%Si

The dezincification in silicon brass (about 15% Zn) had a form of:

- **Pink -copper rich layer.** Zinc and silicon disappeared and the remained area contained pure copper and had a porous microstructure.
- This layer had **porous structure and low microhardness**, and therefore, when appeared on the impeller's blade it exhibited poor mechanical properties and could **failed by erosion**.

UNS C87600:6.6%Zn, 3.37%Si

The dezincification of silicon bronze (about 7% Zn) was characterized by:

- Copper- rich zones on grain boundaries, having a pink color.
- Stress corrosion cracking was developed on the impeller's blade because of mechanical stresses, while dezincification without cracking was observed on the impeller's ring .
- The dezincification of this alloy containing low amount of zinc is attributed to the presence of higher amount of Si, in grain boundaries (>5%) as compared to the matrix (about 2 % Si)